

**INTERVENTO n°5**  
**Planimetria di rilievo**  
**Scala 1:200**

spiazzo in erba

verso  
opera di presa

pista sterrata

verso  
ponte loc. Trivia

ciglio scarpato  
eroso e scavennato

limite acqua  
sponda sx

presenza di piante schiantate in alveo  
e in sponda destra

Torrente  
Ogliolo

S.1

S.1

limite acqua  
sponda sx

ciglio scarpato  
eroso e scavennato



A photograph showing a wide riverbed filled with numerous light-colored, smooth rocks. The riverbed is partially covered with a layer of snow and ice. On the left side, there is a steep, snow-covered bank with some bare trees and shrubs. The right side shows a forested hillside with bare trees. In the background, a mountain range is visible under a cloudy sky.

A wide river flows through a forested valley. The banks are covered in snow, and the riverbed is rocky. The water is dark and turbulent, with white foam visible in the rapids. The surrounding forest consists of bare trees, suggesting a winter or early spring setting. In the background, a mountain peak is visible under a cloudy sky.

A photograph showing a snow-covered landscape. In the foreground, there is a slope covered in snow and scattered rocks. In the background, a dark, rocky ridge or cliff face is visible, partially covered in snow. The overall scene is a winter or high-altitude environment.

A photograph of a snow-covered road in a forest. The road is covered in a layer of snow with some tire tracks. A dark-colored car is visible in the distance on the road. The surrounding area is filled with bare trees and snow-covered ground. The sky is overcast.

 POSIZIONE INDICATIVA RIPRESE FOTOGRAFICHE



LAVORI DI RIPRISTINO DELLE OPERE DI DIFESA IDRAULICA DEL TORRENTE OGILJO POSTE IN ALVEO, ASPORTAZIONE DEL MATERIALE DI DEPOSITO VEGETALE E LITODE, TAGLIO E PULIZIA DELLA VEGETAZIONE SCHIANTATA, AL FINE DI RIPRISTINARE IL CORRETTO PROFILO IDRAULICO DEL TORRENTE PRE-EVENTO OTTOBRE 2020  
CUP: G29J21003360002

Marzo 2023

1:200

9A

INTERVENTO N°5  
PLANIMETRIA DI RILIEVO E VISTE FOTOGRAFICHE  
SCARPATA EROSA IN SPONDA SINISTRA

Committente :  
COMUNE DI EDOLO

A G G I O R N A M E N T I		Data	Descrizione	Redatto	Controllato	Approvato
	f					
	e					
	d					
	c					
	b					
a						

Committente

**Comune di Edolo**  
**Largo Mazzini n°1**  
**tel. 0364/773036**

**Codice Fiscale: 00760070177**

**P. IVA: 00577230980**